

TWR-60036

N91-70089

(NASA-CR-184059) VULCANIZED REPAIR OF

NBR INSULATION Final Report

ASBESTOS (Thiokol Unclas

VULCANIZED REPAIR OF ASBESTOS NBR INSULATION

FINAL REPORT

OCTOBER 1990

#### Prepared for:

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION **GEORGE C. MARSHALL SPACE FLIGHT CENTER** MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812

Contract No.

NAS8-30490

DR. No.

5-3

WBS.No.

4C 102-10-07



P.O. Box 707, Brigham City, UT 84302-0707 (801) 863-3511

\* DOC NO.

VOL.

REV

TITLE

TWR-60036

#### VULCANIZED REPAIR OF ASBESTOS NBR INSULATION

FINAL REPORT

OCTOBER 1990

Prepared by:

K. JENSEN

Elastomers and Adhesives Materials and Processes

Approved by:

K. R. Eckhardt, Manager

Elastomers and Adhesives

Systems Integration Engineer

D. M. Marsh

Program Manager

SR & QA

Thickol CORPORATION SPACE OPERATIONS

P.O. Box 707, Brigham City, UT 84302-0707 (801) 863-3511

Data Management - Release

ECS No. SS 1173



#### Contents

. . .

1.0	INTRODUCTION	1
2.0	OBJECTIVES	1
3.0	SUMMARY	2
4.0	CONCLUSIONS	3
5.0	RECOMMENDATIONS	3
6.0	DISCUSSION	4
6.1	Phase I - Lab Testing	4
6.2	Phase II - Full-Scale Testing	7
	TABLES	
I	Phase I, Lab Study Test Matrix	.11
II.	Phase I, Test Results, Individual, Average and Failure Modes	12
III.	Phase I. Test Results Overview	22
IV.	Revised Phase II, Test Matrix	23
٧.	Phase II, Full-Scale Test Article Surface Vulcanization Repair Test Results, Individual, Average and Failure Modes	24
KEFERENC	ES	27
DISTRIBU	TION	28



#### 1.0 INTRODUCTION

Occurrences of thin insulation, inclusions, defects within the insulation (interlaminate) or defects at the insulation-to-case interface have dictated washout of segment insulation periodically during the SRM and RSRM programs. Previous testing was conducted in the "NBR Rubber Secondary Vulcanization Evaluation Testing" (reported in TWR-50288) which evaluated adding uncured calendared NBR insulation over cured NBR insulation.

The testing discussed in this report was conducted per WTP-0236, "Vulcanized Repair of Asbestos NBR Insulation." The tests outlined in WTP-0236 evaluate various surface preparation materials and methods by applying a layer of uncured calendered rubber to the following three surfaces:

- 1. Existing cured insulation with a patterned surface (used for repair of thin insulation acreage regions).
- Existing cured insulation with a partial layer of the cured insulation removed (simulating repair interlaminar voids).
- 3. Existing insulation with complete removal of insulation to the case wall (both to the Chemlok layer and to the bare metal).

#### 2.0 OBJECTIVES

To evaluate vulcanizing raw calendered NBR to the following cured NBR surfaces:

- 1. Insulation with a patterned surface.
- 2. Insulation with a partial layer of cured material removed.
- 3. Insulation with a complete removal of material to the case wall (both to the Chemlok layer and to the bare metal.)

Assess the influence of the following:

- 1. Cleaning the surface with MEK and with TCA.
- 2. Abrading the surface before solvent cleanup.
- 3. Using a wire brush during the solvent cleaning operation.
- 4. Applying different Chemlok adhesive systems or tackifier as a bonding aid.

TWR-60036				
DOC NO.		VOL		
SEC	PAGE	1		
	DOC NO.			



#### 3.0 SUMMARY

The Phase I test matrix (Table I) consisted of testing (as outlined in the Objective Section) in the Development Lab on witness panels.

Using witness panels enables the tensile buttons to be vulcanized to the NBR layer rather than secondarily bonded. This produces a better bond to the button, preventing adhesive failure at the button bondline. This testing produced 100 percent cohesive failure in the NBR; no bond failure was observed at the vulcanized repair bondline.

Results from the lab testing (individual and average values are provided as Table II and an overview comparison table is provided as Table III) indicate that the Chemlok 233 system, as currently used in the aft dome to vulcanize raw NBR insulation to cured NBR insulation, provides the best bond of the tested surface mediums. Resulting bonds, after cleaning the cured insulation surfaces with MEK or TCA, are very similar. MEK, however, produced slightly higher tensile values. Use of a wire brush or abrading the cured insulation surface during the surface cleaning operation tends to slightly increase the test value strengths.

After evaluating the results from the Phase I testing, the Phase II "Full-Scale Evaluation, Test Matrix" was revised. The revised test matrix is provided in Table IV.

The samples were prepared to evaluate the following:

Sample No. 1 - Surface repairs

Sample No. 2 - Interlaminate repairs

Sample No. 3 - A repair to the case wall with the Chemlok system remaining

Sample No. 4 - A repair to the bare case wall with the Chemlok system removed

The samples were prepared following the test matrix (Table IV). After cure, tensile buttons were secondarily bonded over the patched regions with EA-934 adhesive. The buttons were then pulled by Development Lab personnel using a portable testing apparatus.

Most of the failure was determined to be at the EA-934 adhesive-to-NBR interface. Due to the failure modes observed, it is concluded that the vulcanized bondlines exceed measured strengths. The individual tensile values and failure modes from this testing are provided in Table V.

	TWR-600	36			
REVISION	DOC NO.		VOL		
	SEC	PAGE	2		
FORM TC 7994-310 (REV 2-88)			2		



The current Chemlok 233 system is the best system to repair the surface or interlaminate defects. In addition, the tested methods of the case-to-uncured insulation repairs provide adequate bond values to consider the methods viable processes for repairing regional case-to-insulation defect areas.

#### CONCLUSIONS 4.0

- Chemlok 233 provides the best bond (peel and tensile values) of all the surface mediums tested.
- 2. Solvent cleaning surfaces with MEK or TCA prior to vulcanization results in essentially equivalent peel values. Solvent cleaning with MEK resulted in slightly . higher tensile strengths.
- The surface preparation methods, using the wire brush (to 3. aid in the surface cleanup) and abrasion tended to slightly increase the test strength. The increase, however, is not enough to implement the added operator technique or the additional time involved.
- 4. The failure modes observed on the full-scale tensile testing were at the EA-934 adhesive-to-NBR interface; therefore, it is concluded that the strength of the vulcanized repair bondline is adequate and approaches the strength on the unrepaired insulation.

#### 5.0 RECOMMENDATIONS

#### It is recommended that:

- 1. The current method, proven and used in the aft dome to vulcanize raw NBR insulation to cured NBR insulation, be used to repair thin areas on the insulated segments when additional thickness of insulation is required. method consists of cleaning the cured NBR with MEK, applying one coat of Chemlok 233, allowing it to dry and laying up the required raw NBR calendared material.
- 2. Chemlok 233 be used as the surface preparation medium for any cured NBR to raw NBR repairs and a coat of Chemlok 205 primer and a coat of Chemlok 233 be used when the repair is to the bare metal.
- 3. MEK continue to be used as the cleaning solvent in surface cleanup operations for vulcanized repairs.

	TWR-60036 ,							
REVISION	DOC NO.		VOL					
<del></del>	SEC	PAGE						
FORM TC 7994-310 (REV 2-88)		1	3					



- 4. Abrading of the cloth patterned surface to be repaired or using a wire brush not be conducted on vulcanized repair operations.
- 5. Vulcanized repair of cured NBR to raw NBR or repairs to the case wall as conducted in this testing be considered viable processes for RSRM segment internal insulation operations.

#### 6.0 DISCUSSION

#### 6.1 Phase I Lab Testing

NOTE

Sample Nos. 13 and 15 were fabricated to simulate interlaminate repairs, and Sample Nos. 17 and 18 were fabricated to simulate repairs to the case wall. All other samples were fabricated to simulate the pattern cloth textured surface vulcanized repairs.

#### SAMPLE PREPARATION

Samples were built by technicians in the M-86 Development Lab on witness panel plates. The plates were grit blasted and Chemlok 205 primer and Chemlok 233 were spray applied. Raw 0.100 inch NBR rubber was laid up on all sample panels except Samples Nos. 13 and 15 which had two 0.100 inch raw NBR rubber plies laid up. Sample No. 13 had FEP film between the two layers for easy removal of one-half of the cured insulation to provide 0.100 inch thickness and to provide a shiny surface simulating a void within the insulation. The samples were then autoclave cured.

Variables outlined in the witness panel plates test matrix (Table I) were conducted in fabricating the tensile and peel specimens. MEK and TCA were used to clean the bonding surfaces. A wire brush technique was used during the solvent cleaning operation of specific surface vulcanized repair samples. Abrading of the surface was conducted on two of the textured surface samples, all of the interlaminate repairs and all of the repairs to case wall.

DOC NO. TWR-60036 VOL



Several surface enhancement mediums were also evaluated on the textured surface repairs. They were Chemlok 233 adhesive, Chemlok 236 adhesive, Chemlok 205 primer and Chemlok 233 adhesive, and an MEK base NBR tackifier. The interlaminate and case wall repairs used Chemlok 233 only, except the "case wall" sample which had the Chemlok system removed. Chemlok 205 primer and Chemlok 233 adhesive were used on this sample.

The lab testing determined the current Chemlok 233 system to be the optimum system for surface vulcanized repairs.

- a. Samples 1, 2, 7, 8, 14, and 16 were prepared using Chemlok 233. The average peel strength from these samples was 182.35 pli and the average tensile strength was 610 psi.
- b. Samples 3, 4, 9, and 10 were prepared using Chemlok 236. The average peel strength from these samples was 145.35 pli and the average tensile strength was 537 psi.
- c. Samples 5 and 11 were prepared using Chemlok 205 primer and Chemlok 233 adhesive. The average peel strength from these samples was 144.35 pli and the average tensile strength was 562 psi.
- d. Samples 6 and 12 were prepared using MEK base tackifier. The average peel strength from these samples was 140.4 pli and the average tensile strength was 522 psi.

The samples prepared using Chemlok 233 provided the best peel and tensile test values.

The tested solvents (MEK and TCA) were compared in the Chemlok 233 prepared areas.

- a. Sample 1 surface was cleaned using TCA, producing an average peel value of 181.1 pli and average tensile strength of 584 psi.
- b. Sample 2 surface was cleaned using MEK, producing average peel value of 180.9 and average tensile strength of 593 psi.
- c. Sample 7 was cleaned using TCA and a wire brush to aid in the surface cleaning, producing an average peel value of 186.5 pli and average tensile strength of 598 psi.

	TWR-60	036	•
REVISION	DOC NO.		VOL
	SEC	PAGE	-
FORM TC 7994-310 (REV 2-88)		1	<b>)</b>



- d. Sample 8 was cleaned using MEK and a wire brush to aid in the surface cleaning, producing an average peel value of 180.3 pli and average tensile strength of 639 psi.
- e. Sample 14 surface area was abraded with (approximately) 80 grit cloth and then cleaned with TCA. The resulting average peel value was 178.3 pli and average tensile strength was 606 psi.
- f. Sample 16 surface area was abraded with approximately 80 grit cloth and then cleaned with MEK. The resulting average peel value was 187 pli and the average tensile strength was 642 psi.

The values produced with TCA and MEK were similar, but the MEK produced slightly higher tensile strengths. The surface preparation methods, using the wire brush to aid in the surface cleanup and abrading the surface, tended to slightly aid in the strength, but not enough to implement the added operator technique and the additional time involved.

- g. Sample No. 13 evaluated an interlaminate repair on a shiny surface formed with a layer of FEP film during initial sample preparation. The surface was abraded, cleaned with solvent, brush coated with Chemlok 233, allowed to dry, then raw insulation was laid up. The resulting average peel value was 187.5 pli and the average tensile strength was 450 psi.
- h. Sample No. 15 evaluated an interlaminate repair where a partial layer of the cured insulation had to be removed. The partial layer of insulation was removed using an air chisel. The surface was abraded, cleaned with solvent, brush coated with Chemlok 233, allowed to dry, then raw insulation was laid up. The resulting average peel value was 192.6 pli and the average tensile strength was 424 psi.
- i. Sample No. 17 evaluated insulation repaired to the witness panel Chemlok layer. The sample was prepared by brush applying a coat of Chemlok 233, allowing it to dry, and laying a layer of raw insulation. The resulting average peel value was 163.6 pli and the average tensile strength was 854 psi.

DOC NO. TWR - 60036 VOL



j. Sample No. 18 evaluated insulation repaired to the steel witness panel surface. The Chemlok system was removed, a coat of Chemlok 205 primer and a coat of Chemlok 233 adhesive were brush applied, and allowed to dry, and a layer of raw insulation was laid up. The resulting average peel value was 161.0 pli and the average tensile strength was 817 psi.

Test results from the interlaminate and case wall samples provide sufficient bond strengths to implement these test methods when necessary.

#### 6.2 Phase II Full-Scale Testing

#### NOTE

The witness panel values from this testing cannot be directly compared to production witness panels. These witness panels were fabricated before the final configuration of production witness panels were determined. They differ in that the cured insulation on the panels fabricated for this testing was 0.100 inch thick. The raw insulation applied for the peel specimens was 0.200 inch thick.

Production witness panel specimens of the cured NBR panels have 0.300 inch over the cured layer. The tensile buttons were fabricated with a 0.100 inch raw layer over the cured layer. Production witness panels use 0.050 inch over the cured layer.

The Phase II testing was conducted in the PSA-6 process simulation article in a region that was planned and prepared for this testing. The test matrix (Table IV) used to conduct the full-scale testing was developed by the DR Reduction Team after evaluating the test results from the Phase I testing. This test matrix evaluates:

- 1. Patterned surface repair.
- 2. Interlaminate repair.
- 3. Repair insulation to the case wall, leaving the Chemlok system.
- 4. Repair insulation to the case wall, removing the Chemlok system.

	TWR-60036					
REVISION	DOC NO.		VOL			
<del></del>	SEC	PAGE	-,			
FORM TC 7994-310 (REV 2-88)		1	/			



It was also decided at this time that 9-in. by 9-in. samples instead of the 12-in. by 12-in. samples were sufficient for the Phase II testing. Two test areas were prepared for each sample shown on the test matrix. The "A" samples were constructed from one lot of NBR rubber and the "B" samples were constructed with another lot of NBR rubber to determine possible effects of lot to lot rubber variation.

#### Pattern Surface Repair

SAMPLE PREPARATION - This testing was conducted in a region of the segment where the cured insulation was approximately 0.100-in. thick. The same process used in fabrication of the aft dome to aft barrel insulation joint on an aft segment was employed for the textured surface vulcanized insulation repair. Uncured NBR is vulcanized to previously cured NBR. The surface areas (with a patterning cloth molded surface from the previous cure) were prepared by cleaning the cured insulation surface with MEK. The MEK cleaned areas were allowed to dry 60 minutes. One coat of Chemlok 233 was applied using a foam brush and allowed to dry. One 0.100-in. thick ply of uncured NBR rubber was laid on the Chemlok coated surface of each test region.

#### Interlaminate Repair

SAMPLE PREPARATION - This testing was conducted in an area where the cured insulation was approximately 0.200-in. thick. Approximately 0.100-in. of the cured insulation was removed using an air chisel. This method left an erratic surface. The rubber surface was abraded and cleaned with MEK. The MEK areas were allowed to dry for 60 minutes. One coat of Chemlok 233 was applied using a foam brush and allowed to dry. One layer of 0.100-in. thick ply of uncured NBR rubber was laid over the Chemlok coated surface of each test region.

#### Case Wall to the Chemlok System

SAMPLE PREPARATION - The insulation was removed to the case wall using an air chisel. Care was taken not to damage the cured existing Chemlok System; however, some small minor areas resulted where the bare case was exposed. The remaining surface was carefully abraded to provide a roughened surface and still leave the Chemlok system.

	TWR-600	36	
REVISION	DOC NO.		VOL
FORM TC 7994-310 (REV 2-88)	SEC	PAGE	8
FORM 1C 7334310 (REV 2-00)		1	•



The repair area was cleaned with MEK and allowed to dry for 60 minutes. The few small areas where the bare metal case was exposed were spot painted with Chemlok 205 primer (foam brush applied) and allowed to dry. The entire repair region had one layer of Chemlok 233 applied by foam brush and was allowed to dry. One layer of 0.100 inch thick ply of uncured NBR rubber was laid over the Chemlok coated surface of each test region.

#### Case Wall Chemlok System Removed

SAMPLE PREPARATION - The insulation was removed to the case wall using an air chisel. The remaining Chemlok system was carefully abraded to expose the case wall. The repair area was cleaned with MEK and allowed to dry for 60 minutes. The bare metal of the repair region was coated using a foam brush with Chemlok 205 primer and allowed to dry. The entire repair region had one layer of Chemlok 233 applied by foam brush and was allowed to dry. One layer of 0.100 inch thick ply of uncured NBR rubber was laid over the Chemlok coated surface of each test region.

The entire segment was vacuum bagged and autoclave cured using typical aft segment cure parameters. After cure, the vacuum bag was removed from the segment and tensile adhesion buttons were secondarily bonded over the patched regions using EA-934 adhesive. The adhesive was allowed to dry 24 hours (minimum) prior to testing.

The tensile adhesion buttons were pulled by Development Lab personnel using a portable testing apparatus. Most of the failure was determined to be at the EA-934 adhesive to NBR interface. No bond failure was observed at the NBR to NBR bond interface. Based on the failure modes observed, it is concluded that the strength of the vulcanized repair bondline exceeds these values. These values reflect the strength of the EA-934 to NBR bond.

#### Pattern Surface Repair

Test Results - The average values for the two test areas were 513.6 psi (1A) and 463.6 psi (1B). Individual values are provided in Table V. The average tensile bond strength was 488.6 psi.



#### Interlaminate Repair

Test Results - The average values for the two test areas were 408.4 psi (2A) and 389.8 psi (2B). Individual values are provided in Table V. The average tensile bond strength was 399.1 psi.

#### Case Wall to the Chemlok System

Test Results - The average values for the two test areas were 454.5 psi (3A) and 527.3 psi (3B). Individual values are provided in Table V. The average tensile bond strength was 490.9 psi.

#### Case Wall Chemlok System Removed

Test Results - The average values for the two test areas were 532.3 psi (4A) and 435.5 psi (4B). Individual values are provided in Table V. The average tensile bond strength was 483.9 psi.



# TABLE I. Lab Study Test Matrix

SAMPLE NO:	1	2		3	. 4	. 5		6	. 7		8	. !	9 .	18	. 1	1	12	. 1	3	14	, 1	5	16	. 17	18	
RUBBER LAYUP VARIATION !		) !	1		) [	1	1		! !	1		1	1		1	ı	! }	1	1	 	1	1		; }	1	1
Layup .180 inch thick.	X	   X	1	X	i X	1 1 X	ı	x	! X	1	X	1	X 1	x	ļ	<b>X</b> .	; X	1.		X	1	ı	X	; ;	1 X	1
Layup .200 inch thick.		l	ı		1	1	١		ł	İ		ł	ı		j		١ .	ì	X	)	Ī	X I		1	ı	1
Non-etched FEP fils between the ist and 2nd layer of calendered in NBR rubber.		   	1		   	 	[ ] {		 	   		]	 		! !		   	   	X	   	   			   	   	-! ! !
CURED INSULATION PREPARATION		-  I	<u> </u>		 							- 	<u> </u>	-	1		2	ì					-		· [	=
TCA clean with Rymple cloth.	x	] 	1	x	 	i i X	1	X	   	1		1	1		1		1	1		l I X	1	j		I 1	1	1
MEK clean with Rymple cloth.		ı x	ı		! X	1	1		1	1		1		,	1		1	1	-	!	1	-	<b>X</b> ;	1	1	-! !
Wire brush & TCA clean/dry with   Rymple cloth.		   	1		] 	1	1		ı X	i i		1	X I		! 1	X	ı x	1		i i	1	 !		<u>.</u> ! !	   	-i i i
Wire brush & MEX clean/dry with ! Rymple cloth. !		f I	1		l I	l I	1		I I	1	X	1		X	1		! 1	1		l I	1			! !	1	-1 ! !
Remove layer of insulation above   FEP film.		   	 		 	l I	1		l I	!		 			1		} 	1	X	 	1	1		1	] 	
Using a hand chisel, remove approximately .100 inch   thickness of insulation, leaving   .100 inch thickness.		1	1 1		)     	1	1		]     	]     		1	1		1 1		! ! !	1		 		X 1		t ! !	1 1	]· ] !
Abrade insulation surface with grit emery cloth.		( 	l I		l 1	1 	1		l l	1		1			1		] }	 	x	1 X	i i	X	X	i 1	! 	-:     
Using a hand chisel   remove the insulation to the   metal (Chemlok) surface.		! !	1		1 1	1	1		 	1		   			1		[ ] }	1		     	1 1			] ] X ]	! ! X !	- i
Lightly abrade the Chemlok 233 is surface.		! 1	1		! 1	 	1		 	1		1	ļ				! !	 		   	 			1 X 1	l I	-1 !
Abrade the Chemlok surface, in removing the Chemlok system in as well as possible.		]   	1		]   	  - 	]   		I I I	1		[   	1		   		[ [ ]			\   	1 1 1			] [	1 1 X 1	-,     
SURFACE MEDIUM		l	1		!	I	!		l	ļ		!			I		}	1		!	1			] 	1	<del></del> !
Brush apply 1 coat of Chemlok 233.		1 X	l I		   	1	1		1 1. X	1	X	1			1		 	i	X	1 X	1	X	X	1 X	1	! ! !
Brush apply 1 coat of Chemlok 236.1		1	l	X	1 X	1	J		١	ļ		1	X	X	1		1	1		1	l			l	1	
Brush apply 1 coat of Chemlok 205 / and 1 coat of Chemlok 233.		1	1		 	) X	1		1	1		1	1		1	X	l 1	1		1	1		-	t I	X 	-; -; -
One coat of MEK base tackifier		1				;	[	X	l	ļ		ı			١		1 X	-1		1	١		)	1	1	

	TWR-60036	•	•
REVISION	DOC NO.		VOL
KEAISION	SEC	PAGE	11
FORM TC 7994-310 (REV 2-88)	i		



Table II. Phase I, Test Results, Individual, Average and Failure Modes

#### PEEL TESTS

Sample - Test No.	_	Average Stress PSI	<u>C/A</u>	Failure Mode (%)	A/R
1-1 1-2 1-3 1-4 1-5 Avg. SD CV	181.1 7.3 4.03	179.3 178.0 189.5 187.2 171.5	15 15 15 15 15	5 5 10 10 10	80 80 75 75 75
2-6 2-7 2-8 2-9 2-10 Avg. SD CV	180.9 8.9 4.90	167.9 184.2 190.2 186.1 176.3	10 10 10 10 10	5 10 10 10 10	85 80 80 80 80
3-11 3-12 3-13 3-14 3-15 Avg. SD CV	139.5 1.3 0.93	140.2 137.7 140.0 141.0 138.8	90 90 90 90 90	10 10 10 10 10	
4-16 4-17 4-18 4-19 4-20 Avg. SD CV	149.5 1.8 1.21	147.3 151.1 0 150.9 148.8	90 90 - 90 90	10 10 - 10 10	-

#### LEGEND:

CA = Cohesive in the adhesive (Chemlok)

CR = Cohesive in the rubber

AR = Adhesive at the rubber - Adhesive Interface

REVISION \_\_



Table II. Phase I, Test Results, Individual, Average and Failure Modes (Continued)

Sample - Test No.		Average <u>Stress PSI</u>	Fail <u>C/A</u>	re Mode (%) <u>C/R</u>	A/R
5-21 5-22 5-23 5-24 5-25	1/5 7	149.9 146.6 148.2 146.9	20 20 20 20 20	2 · 2 2 2 2	78 78 78 78 78
Avg. SD CV	145.7 5.0 3.46				
6-26 6-27 6-28 6-29 6-30 Avg.	148.8 2.2	148.2 146.3 148.6 148.6 152.4	- - - -	2 2 2 2 2	98 98 98 98 98
CV 7-31 7-32	1.49	193.5 189.7	15 15	15 15	70 70
7-32 7-33 7-34 7-35 Avg. SD	186.5 7.0	199.7 190.1 183.1 176.0	15 15 15 15	15 15 15 15	70 70 70 70
CV 8-36 8-37 8-38	3.73	175.7 184.7 184.7	10 10 10	10 10 10	80 80 80
8-39 8-40 Avg. SD CV	180.3 5.9 3.30	184.3 172.2	10 10	10 10	80 80
9-41 9-42 9-43 9-44 9-45		149.6 146.7 149.3 145.3 132.3	100 100 100 100 100	- - - -	- - -
Avg. SD CV	144.6 7.1 4.94	LEGEND:	200		

CA = Cohesive in the adhesive (Chemlok)

CR = Cohesive in the rubber

AR = Adhesive at the rubber - Adhesive Interface

	TWR-600	36 ,
REVISION	DOC NO.	VOL
-	SEC	PAGE
EODM TC 7094-310 (REV 2-88)		13



Table II. Phase I, Test Results, Individual, Average and Failure Modes (Continued)

Sample - Test No.		Average <u>Stress PSI</u>	Fail <u>C/A</u>	ure Mode (%) <u>C/R</u>	<u>A/R</u>
10-46 10-47 10-48 10-49 10-50 Avg. SD CV	147.7 4.1 2.77	149.7 150.5 151.3 145.5 141.6	100 100 100 100	- - - -	
11-51 11-52 11-53 11-54 11-55 Avg. SD CV	143.0 4.7 3.30	139.8 148.2 147.4 142.1 137.4	98 98 98 98 98	2 2 2 2 2	
12-56 12-57 12-58 12-59 12-60 Avg. SD CV	132.7 5.2 3.91	129.9 132.0 129.1 130.8 141.8	- - - -	- - - -	100 100 100 100 100
13-61 13-62 13-63 13-64 13-65 Avg. SD CV	187.5 3.0 1.59	188.6 184.4 187.6 185.2 191.4	10 10 10 10	20 10 15 15 25	70 80 75 75 65
14-66 14-67 14-68 14-69 14-70 Avg. SD CV	178.3 12.6 7.06	191.1 182.8 184.6 174.6 158.4 LEGEND:	10 10 10 10 10	10 10 10 10 10	80 80 80 80 80
		CA = Cohe	sive in the	adhesive (Che	mTOK)

CR = Cohesive in the rubber

AR = Adhesive at the rubber - Adhesive Interface



Table II. Phase I, Test Results, Individual, Average and Failure Modes (Continued)

Sample - Test No.		Average Stress PSI	Failu <u>C/A</u>	re Mode (%) <u>C/R</u>	<u>A/R</u>
15-71 15-72 15-73 15-74 15-75 Avg. SD CV	192.6 12.9 6.70	184.8 187.1 205.4 207.3 178.6	10 10 10 10	30 30 35 40 35	60 60 55 50 55
16-76 16-77 16-78 16-79 16-80 Avg. SD CV	187.3 7.0 3.76	177.0 183.8 191.2 195.0 189.6	30 30 30 30 30	20 20 20 20 20	50 50 50 50 50
17-81 17-82 17-83 17-84 17-85 Avg. SD CV	163.6 3.6 2.22	157.3 164.5 164.9 164.6 166.7	- - - -	85 85 85 85 85	15 15 15 15 15
18-86 18-87 18-88 18-89 18-90 Avg. SD CV	161.0 4.4 2.75	154.5 160.4 164.1 166.0 160.0	- - - -	80 80 80 80	20 20 20 20 20 20

#### LEGEND:

CA = Cohesive in the adhesive (Chemlok)

CR = Cohesive in the rubber

AR = Adhesive at the rubber - Adhesive Interface

TWR	-60036	
DOC NO.		VOL
SEC	PAGE	15
	i	10



Table II. Phase I, Test Results, Individual, Average and Failure Modes (Continued)

#### TENSILE TESTS

Sample - <u>Test No.</u>	Ultimate <u>Stress PSI</u>	<u>C/A</u>	Failure Mode ( <u>C/R</u>	%) <u>A/R</u>	<u>FC</u>
1 05	600				
1-25	600	-	100		_
1-26	531	-	95	5	В
1-27	598	-	100	-	
1-28	576 500	-	100	••	
1-29	593	-	100	-	
1-30	593 577	•	100	-	
1-31	577	•	100	-	
1-32	603	•	100	<b>-</b>	
Avg.	584				
SD	23.6				
CV	4.0				
2-33	606	-	100	-	
2-34	529	•	100	<b>100</b>	
2-35	617	-	100	-	
2-36	613	-	100	_	
2-37	652 ·	-	100	_	
2-38	604	-	. 100	_	
2-39	608	-	100	_	
2-40	519	-	100	-	
Avg.	593				
SD	45.5				
CA	7.7				
à .a					
3-41	516	-	100	-	
3-42	621	-	100	-	
3-43	578	-	100	-	
3-44	575	-	100	-	
3-45	536	-	100	-	
3-46	530	•	100	-	
3-47	549	•	100	-	
3-48	494	•	90	10	
Avg.	550				
SD	40.1				
CA	7.3				
			TECEND.		

#### LEGEND:

CA= COHESIVE/ADHESIVE
CR= COHESIVE/RUBBER
AR= ADHESIVE/RUBBER
FC= FAILURE COMMENT
B= BUTTON SIDE
P= PANEL SIDE

DOC NO.	TWR-60036	VOL
SEC	PAGE	16



Table II. Phase I, Test Results, Individual, Average and Failure Modes (Continued)

Sample – Test No.	Ultimate Stress PSI	<u>C/A</u>	Failure Mode (	ቄ) <u>A/R</u>	<u>FC</u>
4-49	451	-	100	<b>-</b> .	
4-50	446	-	100		
4-51	458	esia.	100	<b>45</b>	
4-52	467		100	·-	
4-53	454	•	100	-	
4-54	473	-	100	_	
4-55	535	-	91	9	В
4-56	490	-	100	÷	_
Avg.	472				
SD	29.2				
CV	6.2				
				_	
5-33	581	65	30	5	
5-34	684	5	93	2	
5-35	629	10	80	10	
5-36	615	5	85	10	
5-37	513	50	35	15	
5-38	615	30	60	10	
5-39	521	45	40	15	
5-40	479	45	<b>50</b> .	5	
Avg.	579				
SD	69.4				
CV	12.0				
6-57	535	-	100	_	
6-58	549	-	100	_	
6-59	561	-	100	-	
6-60	574	-	100	-	
6-61	544	•	100	-	
6-62	558	-	100	_	
6-63	562	-	100	-	
6-64	516	-	100	-	
Avg.	550				
SD	18.3				
CA	3.3				
			LEGEND ·		

## LEGEND:

CA- COHESIVE/ADHESIVE
CR- COHESIVE/RUBBER
AR- ADHESIVE/RUBBER
FC- FAILURE COMMENT
B- BUTTON SIDE
P- PANEL SIDE

TWI	R-60036	•
DOC NO.		VOL
SEC	PAGE	17



Table II. Phase I, Test Results, Individual, Average and Failure Modes (Continued)

Sample -	Ultimate	I	Failure Mode (	( <b>%</b> )	
Test No.	Stress PSI	<u>C/A</u>	C/R	<u>A/R</u>	<u>FC</u>
		<del></del>			
7-73	615	-	100	•	
7-74	578	-	100	•	
7-75	611	-	100	٠_	
7-76	525	-	85	15	В
7-77	596	-	100	-	
7-78	623	-	100	-	
7-79	578	-	100	-	
7-80	662	-	100	-	
Avg.	598				
SD	40.1				
CV	6.7				
8-81	608	-	100	-	
8-82	637	•	100	-	
8-83	651	-	100	-	
8-84	659	•	100	-	
8-85	674	-	100	-	
. 8-86	595	-	100	-	
8-87	653	-	100	<b>-</b> .	
8-88	633	-	100	-	
Avg.	639				
SD	26.4				
CA	4.1				
9-89	471	-	80	20	В
9-90	512	-	90	10	В
9-91	614	-	100	-	
9-92	601	-	100	-	
9-93	640	-	100	-	
9-94	548	-	100	-	
9-95	536	-	100	-	
9-96	562	-	100	-	
Avg.	561				
SD	55.9				
CA	10.0		T POEMD.		
			T CCCNTA		

#### LEGEND:

CA- COHESIVE/ADHESIVE
CR- COHESIVE/RUBBER
AR- ADHESIVE/RUBBER
FC- FAILURE COMMENT
B- BUTTON SIDE
P- PANEL SIDE

7	R-60036	
DOC NO.	\	/OL
SEC	PAGE	1.0



Table II. Phase I, Test Results, Individual, Average and Failure Modes (Continued)

Sample -	Ultimate		Failure Mode (%	)	
Test No.	Stress PSI	<u>C/A</u>	<u>C/R</u>	<u>A/R</u>	<u>FC</u>
10-97	558	-	100	-	
10-98	571	-	100	-	
10-99	615	-	100	· <del>-</del>	
10-100	540	-	100	-	
10-101	-	-	-	-	
10-102	575	-	100	-	
10-103	<b>569</b>	•	100	-	
10-104	510	-	100	-	
Avg.	563				
SD	32.7				
CA	5.8				
11-81	609	_	100	_	
11-82	577	_	94	6	
11-83	613	· •	100	-	
11-84	523	_	90	10	
11-85	523	_	98	2	
11-86	593	_	96	4	
11-87	563	_	97	3	
11-88	555	_	98	2	
Avg.	569			_	
SD	35.0				
CV	6.1				
10 65	0754				-
12-65	275*	-	45	55	В
12-66	571	-	100	-	_
12-67	488	-	84	16	В
12-68 12-69	538 432	-	74	26	В
		-	100	-	
12-70	586 577	-	100	-	
12-71 12-72	577 484	-	100	-	
		-	100	-	
Avg. SD	532.7				
	59.5		Todom.		
CA	11.4		LEGEND:		

<sup>\* =</sup> Outlier, not included in calculations

CA- COHESIVE/ADHESIVE
CR- COHESIVE/RUBBER
AR- ADHESIVE/RUBBER
FC- FAILURE COMMENT
B- BUTTON SIDE
P- PANEL SIDE

	TWR-60	036	•
REVISION	DOC NO.		VOL
	SEC	PAGE	10
FORM TC 7994-310 (REV 2-88)		ı	19



SPACE OPERATIONS

Table II. Phase I, Test Results, Individual, Average and Failure Modes
(Continued)

Sample -	Ultimate		Failure Mode (%	)	
Test No.	Stress PSI	<u>C/A</u>	<u>C/R</u>	<u>A/R</u>	<u>FC</u>
13-105	512	-	40	60 <sub>.</sub>	P
13-106	406	108	20	80	P
13-107	432	-	20	80	P
13-108	508	-	40	60	P
13-109	511	-	40	60	P
13-110	358	-	40	60	P
13-111	353	-	25	75	P
13-112	520	•	50	50	P
Avg.	450				
SD	71.7				
CA	15.9				
14 101	EOO		100		
14-121 14-122	598 669	-	100 100	-	
	583	•		-	
14-123	562	-	100	-	
14-124		•	100	10	D
14-125	460 691	-	90	10	P
14-126		-	100	10	
14-127 14-128 .	632 653	-	90	10	
	606	•	100	-	
Avg.					
SD	73.5				
CA	12.1				
15-113	404	-	70	30	B/P
15-114	517	-	65	35	B/P
15-115	394	-	45	55	P <sup>'</sup>
15-116	427	-	45	55	P
15-117	414	-	55	45	P
15-118	398	-	55	45	P
15-119	430	-	55	45	P
15-120	406	-	65	35	P
Avg.	424		-		_
ຮກິ	39.9				
CV	9.4				
			i rcrnd •		

#### LEGEND:

CA=	COHESIVE/ADHESIVE
CR=	COHESIVE/RUBBER
AR=	ADHESIVE/RUBBER
FC-	FAILURE COMMENT
B=	BUTTON SIDE
.P=	PANEL SIDE

TWR-60036				
DOC NO.	VOL			
SEC	PAGE	20		



Table II. Phase I, Test Results, Individual, Average and Failure Modes (Continued)

Sample -	Ultimate `		Failure Mode (	<b>%</b> )	
Test No.	Stress PSI	<u>C/A</u>	<u>C/R</u>	A/R	<u>FC</u>
16 100	657		100		
16-129 16-130	657 699	•	100 100	<del>-</del> .	
16-131	631	•	100	-	
16-132	643		100	·	
16-133	651	-	100	<b>.</b>	
16-134	639		100	_	
16-135	547	_	100	_	
16-136	672	_	100	_	
Avg.	642	-	100	-	
SD.	44.1				
CA	6.9				
	0.7				
17-137	891	_	100	<b>60</b>	
17-138	813	-	100	•••	
17-139	857	_	100	-	
17-140	863	-	100	-	
17-141	849	-	100	_	
17-142	847	-	100	_	
17-143	882	٠.	100	-	
17-144	829	-	100	-	
Avg.	854				
SD	25.5				
CV	3.0				
18-137	838	-	95	5	
18-138	792	-	95	5	
18-139	802	-	95	5	
18-140	788	-	97	3	
18-141	842	-	90	10	
18-142	846	-	93	7	
18-143	832	-	93	7	
18-144	802	-	96	4	
Avg.	817				
SD	23.9				
CA	2.9				
			I FCFND ·		

#### LEGEND:

CA=	COHESIVE/ADHESIVE
CR-	COHESIVE/RUBBER
AR-	ADHESIVE/RUBBER
FC=	FAILURE COMMENT
B-	BUTTON SIDE
·P-	PANEL SIDE

	WR-60036	l
DOC NO.		VOL
SEC	PAGE	21

		Table III.	Phase I,	Test	Results,	Phase I, Test Results, Overview	
	Sample No.	Peel Results	TCA	MEK	Wire Brush	Abrade	Tensile Results
Chemlok 233	1 7 14 14	181.1 180.9 186.5 180.3 178.3	<b>*</b> * *.	× ×	××	××	584 593 598 639 606
(Case)	17	167. 163.6		∢		<b>4</b> ×	854
(Interlaminate) (Interlaminate)	) 13 ) 15	187.5 187.				××	450 424
Chemlok 236	3 4 9 10	139.5 149.5 144.7 147.7	××	<b>×</b> ×	××		550 472 561 563
Chemlok 205/ 233 (Case)	5 11 18	145.7 143. 161.	××		×	×	561 563 817
Tackifier	6 12	148.8 132.7	××		×		550 493



#### Table IV. Revised Phase II Test Matrix

	1	2	SAMPLE 3	NO. 4
CURED INSULATION PREPARATION				
Using a hand chisel, remove approximately 0.100-inch thickness of insulation, leaving approximately 0.100-inch thickness		x		
Using a hand chisel, remove the insulation to the metal (Chemlok) surface			X	x
Abrade insulation surface with 80-100 grit cloth		X		
Lightly abrade the Chemlok 233 surface			X	
Abrade the Chemlok surface, removing the Chemlok system as well as possible				x
MEK clean with Rymplecloth	х	X	X	x
SURFACE MEDIUM				
Brush apply one coat of Chemlok 233	x	x	x	
Brush apply one coat of Chemlok 205 and one coat of Chemlok 233				X

TWI	R-60036 .	
DOC NO.		VOL
SEC	PAGE	23



Table V. Full-Scale Test Article Surface Vulcanization Repair Pattern Surface Repair

#### TENSILE VALUES

Failure Mode (%)

Ultimate

	Stress				
<u>Test</u>	<u>No. (psi)</u>	AMF	AIF	<u>HI</u>	<u> </u>
1A-1	334*	95		1	4
1A-2	594		75	25	
1A-3	561		70	30	
1A-4	457		90	10	
1A-5	443		90	10	
Avg	513.6				
SD	75.0				
CA	14.6%				

Failure Mode (%)

Ultimate

	Stress				
Test No.	(psi)	AMF	AIF	HI	HA
_					
1B-1	412	99		•	1
1B-2	556		90	10	
1B-3	189*	95	4	(1% VO	ID)
1B-4	406		85	15	•
1B-5	481		90	10	
Avg	463.6				
SD	70.4				
CA	15.2%				

<sup>\*</sup> Considered an outlier- Not used in these calculations

#### LEGEND:

AMF- Adhesive/Metal Interface

AIF- Adhesive/Insulation Interface

HI= Cohesive/ Insulation

HA- Cohesive/ Adhesive

TWR-60036 DOC NO. VOL SEC PAGE 24

REVISION



Table V. Full-Scale Test Article Surface Vulcanization Repair (Continued)

# Interlaminar Repair Failure Mode (%)

	Ultimate Stress				
Test No.	(psi)	AMF	AIF	HI	<u>HA</u>
2A-6	357		50	45	5% VOID
2A-7	442		50	50	
2A-8	413		45	45	10% VOID
2A-9	411		50	50	
2A-10	420		50	50	
Avg	408.4				
SD	31.2				
CA	7.6%				

#### Failure Mode (%)

Test No	Ultimate Stress	AMF	AIF	HI_	НА
2B-6	426		<sup>*</sup> 50	50	
2B-7	408		45	45	10% VOID
2B-8	397	40	20	20	20% VOID
2B-9	309		35	30	35% VOID
2B-10	409		50	45	5% VOID
Avg	389.8				
SD	46.1				
CA	11.8%				

#### Case Wall Chemlok System Removed Failure Mode (%)

#### Ultimate Stress AMF Test No. (psi) AIF HI HA 3A-1 357\* 95 1 4 3A-2 453 95 5 3A-3 437 95 5 3A-4 492 95 5 3A-5 534 85 15 Avg 454.5 LEGEND: 66.3 AMF- Adhesive/Metal Interface SD CV 14.6% AIF- Adhesive/Insulation Interface HI= Cohesive/ Insulation HA- Cohesive/ Adhesive

### \* Considered an outlier- Not used in these calculations

REVISION	DOC NO. TWR-60036		
- <del></del>	SEC	PAGE 25	
FORM TC 7994-310 (REV 2-88)		25	



SPACE OPERATIONS

#### Table V. Full-Scale Test Article Surface Vulcanization Repair (Continued)

#### Failure Mode (%)

					,	
	Ultimate					
	Stress					
Test No.	(psi)	AMF	AIF	HI	<u>HA</u>	
3B-1	438		70	28	2%	VOID
3B-2	550		50	50		
3B-3	464		44	44	12%	VOID
3B-4	508	85	10	5		
3B-5	676		30	70		
Avg	527.3					
SD	93.3					
CV	17.7%					

#### Case Wall Chemlok System Removed Failure Mode (%)

U1	timate	
Q	trocc	

		Stress				
_	Test No.	(psi)	AMF	AIF	HI	<u>HA</u>
	4A-6	540		40	60	
	4A-7	509		40	60	
	4A-8	582		40	60	
	4A-9	488	60	20	20	
	4A-10	543	10	40	50	
	Avg	532.3				
	SD	36.0				
	CA	6.8%				

#### Failure Mode (%)

#### Ultimate Stress

VOID
VOID

Avg	435.5
SD	77.4
CV	17.8%

#### LEGEND:

AMF- Adhesive/Metal Interface

AIF- Adhesive/Insulation Interface

HI= Cohesive/ Insulation

HA- Cohesive/ Adhesive

REVISION	TWR-6003	DOC NO. TWR-60036		
	SEC	PAGE		
FORM TC 7994-310 (REV 2-88)		1	26	



#### REFERENCES

- 1. Jensen, S.K., "NBR Rubber Secondary Vulcanization Evaluation Testing", TWR-50288
- 2. Jensen, S.K., "Vulcanized Repair of Asbestos NBR Insulation", WTP-0236
- 3. Witness Panel Testing, Inert Material Mechanical Testing Lab, LWR-594841, May 1990
- 4. Witness Panel Testing, Inert Material Mechanical Testing Lab, LWR-589553, June 1990
- 5. Witness Panel Testing, Inert Material Mechanical Testing Lab, LWR-589917, July 1990

REVISION \_\_\_\_\_ DOC NO. TWR - 60036 VOL SEC PAGE 27

# Thickol CORPORATION SPACE OPERATIONS

DISTRIBUTION			
L. D. Allred	L72		
S. L. Archibald	692		
F. B. Baugh	L62		
I. N. Black	L71		
J. R. Braithwaite	L71		
K. R. Eckhardt	E80		
N. F. Eddy	L62B		
S. G. Foth	812		
M. M. Hash	E80		
J. S. Jensen	692		
S. K. Jensen	E80		
G. J. Jepson	L82		
D. M. Ketner	L63		
R. D. Larsen	851B		
J. D. Leavitt	650		
B. J. Loveland	654		
M. B. Mackey	362		
S. D. Mildenhall	E80		
P. C. Petty	L82		
T. F. Pinkerman	MSFC		
R. L. Schiffman	691		
L. E. Seidner	E80		
W. A. Smith	694		
E. M. Vallejos	812		
C. R. Whitworth	E80		
Print Crib (5 Copies)	E80		

TWR-60036 VOL SEC PAGE 28